

Sprinkler Tanks Barclays - Canary Wharf



CASE STUDY

We were commissioned to carry out a confined space inspection of two existing concrete sprinkler tanks at a commercial facility in Canary Wharf.

Problem

Following client approval, we mobilised to site and completed all preparatory works, including abrasive surface preparation and moisture testing. The GRP lining system was then installed to both tanks, providing a seamless, corrosion-resistant barrier.

Installation

The client was satisfied with the outcome and has since engaged us for further remedial works across the facility.

Feedback

Solution

The inspection was conducted in full compliance with health and safety protocols, including gas monitoring and rescue provisions. Our team identified areas of surface degradation and confirmed the suitability of GRP lining as a long-term solution.

Completion

All works were completed within the agreed timeframe and with minimal disruption to site operations. Final inspections confirmed full adhesion and integrity of the lining system.



