

Swimming Pool Refurbishment

Plymouth College



CASE STUDY

We were approached by a pool and spa specialist seeking our assistance with GRP lining works to rejuvenate a tired and worn swimming pool located in Plymouth.

Problem

Following approval, we commenced extensive preparation works using a specialist shot blasting method to ensure the substrate was sound and suitably prepared. Once satisfied with the surface condition, we progressed with the GRP lining installation over a carefully managed two-week programme.

Installation

With the project successfully wrapped up and the site fully cleared, we received highly positive feedback from the client, who expressed their genuine satisfaction with the finished result and commended the quality of the workmanship throughout.

Feedback

Solution

To ensure our quotation was both accurate and reflective of the project requirements, we conducted a detailed site visit to gain a clear understanding of the condition and scope of the swimming pool.

Completion

After applying the final topcoat to deliver a premium finish, we added a striking visual element by incorporating the college logo at the pool's base along with bold dark blue lane markings, further elevating the pool's aesthetic and functionality.

