

Washeteria Cold Water Storage Tank



CASE STUDY

A heavily corroded sprinkler tank at a busy laundrette in Royal Tunbridge Wells was flagged as potentially beyond repair, leaving the client uncertain whether it could be salvaged.

Problem

We began with heavy mechanical preparation, removing all corrosion and creating a reliable key for optimal adhesion. Once the substrate was fully prepared, we installed our high-performance GRP lining system, designed to withstand the demands of the laundrette's operational environment.

Installation

Our client was beyond impressed with the finished results and sent a huge thank you to the team on site. What was once a doubtful case became a showcase of how technical expertise and preparation can truly save the day.

Feedback

Solution

The internal surfaces were extensively rusted, raising serious concerns about its structural integrity and long-term performance. After a detailed inspection, our team proposed a full GRP lining solution to restore and protect the tank.

Completion

The transformation was immediate—clean, durable, and fully sealed. The client was genuinely impressed, not only with the visual result but with the reassurance of long-term protection.



